



APPENDIX A: Finchley Lido Remedial Photos


Main Pool: Extent of propping & scaffolding



Main Pool: Enabling access to roof / structure



Structure: Access to enable intrusive surveys



Structure: Access to timber beams and connections



Access: Removal of ducting and apex connections