

BX H&G Appendix 1 - Brent Cross West Site Progress Pictures – August 2022

DETAILED PICTURES ON PAGE 2

1. **Fourways** installing CMS and wiring to aid CCTV installation on SEEB Gulam columns
2. **Advanced Glass** continued panel installation to entrance frame of EOB
3. **3.1 Adept** finished internal walls of managers room on West and
3.2 to be finished on East. GL 3-6 to BOH office
4. **Cavers** installing steelwork on WEB
5. **PLS** continued shuttering stairs to be poured
6. **Adept** installing SFS to steel work at WEB
7. **7.1 Fast Platform: Carvers** aligning lower canopies
7.2 OCL air testing main drainage from FXH35 to FXH00
8. **8.1 Slow Platform:** Installation of manhole frame northern end. Manhole benching of manhole northern and southern end
8.2 Continued with block paving around manhole northern end. Installation of hydraulic hoses LMR
9. Station elevation

BXW Station looking East to West



